



VEHICLE INSPECTION REPORT

YA70CNO

Land Rover Discovery Sport 1.5 P300e R-Dynamic S 5dr Auto [5 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	10/12/2020	Body Style	Estate	Last service miles	59,040
Year	2020	Keys	2	MOT Due	09/12/2026
Mileage	66,609 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Hybrid Electric	Service documents	Printout	Gears	8
Colour	WHITE	Number of stamps	4		
VIN	SALCA2AT0LH881697	Last service date	04/08/2025		

Last service 04/08/2025 at 59,040 miles- 4 services

Tyres



NSF	PIRELLI	4.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	OK
OSR	PIRELLI	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Solid Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Door osf
Chipped
Edge Chip



3: Wheel osr
Scratched
Up To 50mm



4: Door nsr
Chipped
1 To 5



5: Bumper Front
Chipped
Multiple Chips



6: A Post os
Poor Previous Repair
Poor Paint



7: Roof
Poor Previous Repair
Poor Paint



8: A Post ns
Poor Previous Repair
Poor Paint



9: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK