

VEHICLE INSPECTION REPORT

YE12SSJ

Peugeot 107 1.0 Allure 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	18/05/2012	Colour	RED	MOT Due	30/09/2026
Year	2012	VIN	VF3PNCFB488653513	Gearbox	MANUAL
Mileage	94,105 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Petrol	Keys	2	Doors	5

Tyres

NSF	BUDGET	1.9mm
NSR	TOYO	5.0mm
OSF	BUDGET	3.0mm
OSR	PIRELLI	3.0mm
Spare		

Features


- Rear wiper
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Radio/CD
- Rear headrests
- Passenger airbag
- Alloy wheels
- Body coloured bumpers
- Solid Paint
- Central locking
- Air conditioning
- ABS
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Scratched
Over 50mm



2: Door Mirror Assy of
Scratched (Painted)
Up To 25mm Thru Paint



3: Other
N/A
N/A




4: Other
N/A
N/A



5: Bumper Rear
Poor Previous Repair
Paint Flake



6: Wheel nsr
Scratched
Up To 50mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wing nsf
Dented
Over 30mm



9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Poor Previous Repair
Paint Flake



11: Bonnet
Chipped
Multiple Chips



12: Screen Front
Chipped
UpTo 10mm



13: Wing osf
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK