



# VEHICLE INSPECTION REPORT

**GY61MWZ**

## Audi A6 Allroad 3.0 TDI Quattro 5dr Tip Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	11/11/2011	Body Style	Estate	Last service miles	143,034
Year	2011	Keys	2	MOT Due	21/07/2026
Mileage	152,034 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6		
VIN	WAUZZZ4F8BN081672	Last service date	18/06/2025		

£90 ADDITIONAL FEE

LAST SERVICE 18/06/2025 @ 143,034 MILES (6 SERVICES, 2 MAIN DEALER - BOOK & PRINT) Service due message displayed

### Tyres

NSF	ROTALLA	5.0mm
NSR	NEXEN	Damaged
OSF	IMPERIAL	5.0mm
OSR	NEXEN	3.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips




3: Wing nsf  
Chipped  
1 To 5



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Other  
N/A  
N/A



11: Roof  
Dented  
Between 10mm + 30mm



12: Wheel osr  
Scratched  
Over 50mm



13: Qtr Panel osr  
Dented  
Between 10mm + 30mm



14: Door osr  
Chipped  
1 To 5



15: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



16: Door osf  
Chipped  
1 To 5



17: Wing osf  
Chipped  
Multiple Chips



18: Wheel osf  
Scratched  
Over 50mm



19: Screen Front  
Cracked  
Replace



20: Tyre nsr  
Damaged  
Replace



21: Bonnet  
Dented  
Between 10mm + 30mm

**Interior**

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK