



VEHICLE INSPECTION REPORT

BG18FYY

Nissan Qashqai 1.2 DiG-T N-Connecta 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/03/2018	Body Style	Hatchback	Last service miles	84,611
Year	2018	Keys	2	MOT Due	21/04/2027
Mileage	84,615 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	8	Doors	5
VIN	SJNFEAJ11U2229444	Last service date	22/04/2026		

LAST SERVICE 22/04/2026 @ 84,611 MILES (8 SERVICES, 4 MAIN DEALER - BOOK AND PRINT)

Tyres




NSF	RAPID	6.0mm
NSR	GOODYEAR	3.0mm
OSF	RAPID	5.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Dented
Between 10mm + 30mm



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Qtr Panel osr
Chipped
Edge Chip



6: Tailgate
Chipped
1 To 5



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Door nsr
Chipped
1 To 5



10: Door nsf
Chipped
1 To 5



11: Wing nsf
Dented
2 Or Less UpTo 10mm




12: Wheel nsf
Scratched
Up To 50mm



13: Bumper Front
Scratched
UpTo 25mm Thru Paint



14: Bonnet
Chipped
1 To 5



15: Glass Roof
Chipped
UpTo 10mm



16: Lamp osr
Broken
Replace



17: Bumper Rear
Chipped
1 To 5



18: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



19: Screen Front
Chipped
UpTo 10mm



20: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		