

VEHICLE INSPECTION REPORT

GU73HKG

Toyota Yaris 1.5 Hybrid GR Sport 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	02/09/2023	VIN	VNKKBAC390A281814	CAP Average	£17,000.00
Year	2023	Body Style	Hatchback	CAP Below	£15,850.00
Mileage	11,993 Miles Warranted	Keys	2	Gearbox	CVT
Fuel Type	Hybrid Electric	Service history	None	Gears	1
Colour	GREY	CAP Clean	£18,200.00	Doors	5

£65 ADDITIONAL FEE NO SERVICE HISTORY OR MOTS DONE YET



Tyres

NSF	BRIDGESTONE	2.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BUDGET	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel nsr
Scratched
Up To 50mm



2: Wheel nsf
Scratched
Over 50mm



3: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK