

VEHICLE INSPECTION REPORT

GD14SYX

Suzuki SX4 1.6 SZ5 4X4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
 GRADE
3

Details

Reg. date	25/06/2014	Colour	RED	MOT Due	24/06/2026
Year	2014	VIN	TSMEYB21S00817084	Gearbox	MANUAL
Mileage	45,375 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Petrol	Keys	2	Doors	5

Some panels require machine polish

Tyres

NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Door nsr
Chipped
1 To 5



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Tailgate
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing of
Chipped
1 To 5

16: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK