



# VEHICLE INSPECTION REPORT

**WP11WNC**

## HYUNDAI IX20 1.4 Blue Drive Style 5dr

### Inspection

### Vehicle

|     |         |
|-----|---------|
| VAT | Margin  |
| V5  | Present |

### Details

|                  |                            |                          |                   |                           |            |
|------------------|----------------------------|--------------------------|-------------------|---------------------------|------------|
| <b>Reg. date</b> | 13/07/2011                 | <b>VIN</b>               | TMAPU81CLBJ035117 | <b>Last service date</b>  | 26/08/2025 |
| <b>Year</b>      | 2011                       | <b>Body Style</b>        | MPV               | <b>Last service miles</b> | 105,973    |
| <b>Mileage</b>   | 113,882 Miles<br>Warranted | <b>Service history</b>   | Yes               | <b>MOT Due</b>            | 25/08/2026 |
| <b>Fuel Type</b> | Petrol                     | <b>Service documents</b> | Service Book      | <b>Gearbox</b>            | MANUAL     |
| <b>Colour</b>    | WHITE                      | <b>Number of stamps</b>  | 14                | <b>Gears</b>              | 5          |

£100 ADDITIONAL FEE.

Clutch, water pump & drive belt replaced 27/01/2026.

Last service 26/08/2025 at 105973 miles (14 services (5 main dealer). Book & print.

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |