



# VEHICLE INSPECTION REPORT

**GV24YDY**

## Vauxhall Astra 1.2 Turbo 130 GS 5dr

nama  
GRADE  
**2**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	09/07/2024	Body Style	Hatchback	Last service miles	19,372
Year	2024	Keys	2	Gearbox	MANUAL
Mileage	23,007 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	YELLOW/BLACK	Number of stamps	2		
VIN	VXKFPHNSLR1011410	Last service date	22/10/2025		

£90 ADDITIONAL FEE.

Last service 22/10/2025 at 19372 miles (2 services). Spanner light on dash

### Tyres

NSF	PIRELLI	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	PIRELLI	5.0mm
OSR	MICHELIN	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

## Photos





## Condition Check




## Damage Photos




1: Roof Lining  
Scuffed  
Over 25mm




2: Bonnet  
Chipped  
1 To 5




3: Wheel nsf  
Scratched  
Over 50mm




4: Door nsf  
Chipped  
Edge Chip




5: Door nsf  
Scratched  
Over 25mm Not Thru Paint




6: Qtr Panel osr  
Dented  
Between 10mm + 30mm



7: Door osr  
Dented  
Between 10mm + 30mm



8: Roof  
Scratched  
Over 25mm Thru Paint



9: Wheel osf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition**            Average  
**Seat Condition**            Average

**Upholstery Condition**    Average  
**Odour**                        No

**Vehicle Inspection Report**

---

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

**Additional fees may apply to some vendors.**  
**Please note buyers rate increase from 01/01/2025**

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK