



VEHICLE INSPECTION REPORT

GF17PVZ

BMW 1 Series M140i 5dr [Nav] Step Auto

nama
GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/03/2017	Colour	BLUE	MOT Due	13/02/2027
Year	2017	VIN	WBA1S920905H00960	Gearbox	AUTOMATIC
Mileage	100,007 Miles Warranted	Body Style	Hatchback	Gears	8
Fuel Type	Petrol	Keys	2	Doors	5

£90 ADDITIONAL FEE. Some panels require machine polish
 After market exhaust fitted
 Car lowered

Tyres


NSF	GOODYEAR	5.0mm
NSR	MICHELIN	5.0mm
OSF	GOODYEAR	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Dented
With Paint Damage




3: Wing nsf
Poor Previous Repair
Poor Paint



4: Door nsf
Chipped
1 To 5



5: Roof
Dented
Over 30mm



6: Door osr
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Wheel osr
Scratched
Up To 50mm



10: Door osr
Chipped
Edge Chip



11: Door osf
Chipped
Edge Chip



12: Wing osf
Dented
Over 30mm



13: Screen Front
Chipped
Up To 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK