



VEHICLE INSPECTION REPORT

NX17XUE

Volkswagen Polo 1.0 Beats 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Photocopy

nama
GRADE
3

Details

Reg. date	15/03/2017	Body Style	Hatchback	Last service miles	61,455
Year	2017	Keys	1	MOT Due	25/03/2027
Mileage	65,241 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	5
Colour	BLACK	Number of stamps	9	Doors	3
VIN	WVWZZZ6RZHY202939	Last service date	24/03/2025		

£90 ADDITIONAL FEE.

NO V5 PHOTOCOPY ONLY.

LAST SERVICE 24/03/2025 @ 61,455 MILES (9 SERVICES, ALL MAIN DEALER) Service due message displayed

Some panels require machine polish

Tyres

NSF	BUDGET	4.0mm
NSR	BRIDGESTONE	3.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	5.0mm

Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door nsf
Chipped
Edge Chip



5: Qtr Panel nsr
Dented
Over 30mm



6: Qtr Panel nsr
Rusted
Over 5mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Door osf
 Scratched
 Over 25mm Thru Paint

10: Wing osf
 Dented
 2 Or Less UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK