



VEHICLE INSPECTION REPORT

GJ62YCT

Ford Focus 1.0 EcoBoost Edge 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	09/10/2012	Body Style	Hatchback	Last service miles	128,445
Year	2012	Keys	2	MOT Due	17/08/2026
Mileage	133,000 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	12	Doors	5
VIN	WF0KXXGCBKCD66881	Last service date	12/08/2025		

£100 ADDITIONAL FEE

Last Service - 12.08.2025 at 128445 miles (12 services) Engine tapping
 Abs and traction light on
 Front suspension knocking while turning broke spring

Tyres


NSF	SUNNY	5.0mm
NSR	BUDGET	4.0mm
OSF	SUNNY	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Rear parking sensor
- Electric door mirrors
- Solid Paint
- Traction control
- Steel wheels
- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Wing osf
Chipped
1 To 5




2: Door osf
Chipped
1 To 5




3: Other
N/A
N/A




4: Door osr
Chipped
1 To 5




5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




6: Qtr Panel osr
Chipped
1 To 5




7: Bumper Rear
Poor Previous Repair
Poor Paint




8: Tailgate
Rusted
UpTo 5mm




9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




10: Door nsr
Chipped
1 To 5




11: Door nsr
Scratched
Over 25mm Not Thru Paint




12: Door nsf
Scratched
Over 25mm Not Thru Paint




13: Wing nsf
Scratched
Over 25mm Not Thru Paint



14: Bumper Front
Chipped
Multiple Chips



15: Bumper Front
 Scratched
 Over 25mm Not Thru Paint



16: Bonnet
 Chipped
 1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	Fault		
Windows	OK	Radio	OK
		Steering	OK