



VEHICLE INSPECTION REPORT

LG08ZYZR

Mini Convertible 1.6 Cooper 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	25/04/2008	Colour	WHITE	Service history	None
Year	2008	VIN	WMWRF32070TN06814	MOT Due	05/06/2026
Mileage	97,037 Miles Warranted	Body Style	Convertible	Gearbox	MANUAL
Fuel Type	Petrol	Keys	1	Gears	5

£100 ADDITIONAL FEE
No service history Oil light is on

Tyres

NSF	FARROAD	4.0mm
NSR	FARROAD	4.0mm
OSF	FARROAD	4.0mm
OSR	FARROAD	4.0mm
Spare		

Features


- Radio/CD
- Air conditioning
- ABS
- Central locking
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Remote central locking
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Leather seat trim
- Electric sunroof
- Solid Paint
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osf
Scratched
Over 25mm Not Thru Paint



5: Wheel osr
Corroded
Light



6: Bumper Rear
Poor Previous Repair
Paint Flake



7: Tailgate
Rusted
UpTo 5mm



8: Wheel nsr
Corroded
Light



9: Qtr Panel nsr
Scratched
UpTo 25mm Not Thru Paint



10: Door nsf
Chipped
1 To 5



11: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Bonnet
Chipped
1 To 5



15: Bonnet
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK