



# VEHICLE INSPECTION REPORT

**EF63EKD**

## Vauxhall Astra 1.6i 16V Excite 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	10/01/2014	Body Style	Hatchback	Last service miles	86,188
Year	2014	Keys	2	MOT Due	09/01/2027
Mileage	111,918 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	5	Doors	5
VIN	W0LPC6ED9E1053722	Last service date	26/10/2023		

LAST SERVICE 26/10/2023 @ 86,188 MILES (5 SERVICES, 3 MAIN DEALER- BOOK AND PRINT) Exhaust blowing  
Multiple panels will need machine polish  
Coolant leak

### Tyres

NSF	FARROAD	5.0mm
NSR	BUDGET	4.0mm
OSF	FARROAD	4.0mm
OSR	BUDGET	4.0mm

### Spare

## Features


- Bluetooth connection
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
1 To 5



3: Door osr  
Chipped  
1 To 5



4: Door osr  
Dented  
2 Or Less UpTo 10mm



5: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



6: Bumper Rear  
Poor Previous Repair  
Poor Paint



7: Tailgate  
Dented  
2 Or Less UpTo 10mm



8: Qtr Panel nsr  
Chipped  
1 To 5



9: Door nsr  
Chipped  
Multiple Chips



10: Door nsf  
Chipped  
1 To 5



11: Wheel nsf  
Scratched  
Over 50mm



12: Wing nsf  
Chipped  
1 To 5



13: Bonnet  
Chipped  
1 To 5



14: Roof  
Poor Previous Repair  
Paint Flake



15: Seat Back Cover of  
Scuffed  
Over 25mm

**Interior**

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK