

# VEHICLE INSPECTION REPORT

**EO11WNT**

## Ford Focus 1.6 Titanium 5dr

nama  
GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	24/03/2011	Body Style	Hatchback	Last service miles	43,878
Year	2011	Keys	2	MOT Due	17/02/2027
Mileage	57,454 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	5	Doors	5
VIN	WF0PXXGCDPAP48901	Last service date	22/06/2018		

last service 22/6/18 @ 43,878 miles (5 services 2 main dealer) book & print Multiple panels need machine polish


### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Heated front seat
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Door osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
Edge Chip



4: Door osr  
Chipped  
1 To 5



5: Wheel osr  
Scratched  
Over 50mm



6: Bumper Rear  
Dented  
With Paint Damage



7: Reflector nsr  
Broken  
Replace



8: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



9: Wheel nsr  
Scratched  
Over 50mm



10: Door nsr  
Chipped  
1 To 5



11: Door nsr  
Dented  
2 Or Less UpTo 10mm



12: Door nsf  
Chipped  
1 To 5



13: Wing nsf  
Scratched  
Over 25mm Thru Paint



14: Wheel nsf  
Scratched  
Over 50mm



15: Bumper Front  
 Scratched  
 25 to 100mm Thru Paint



16: Bumper Front  
 Chipped  
 Multiple Chips



17: Bonnet  
 Chipped  
 1 To 5



18: Screen Front  
 Chipped  
 UpTo 10mm

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK