

VEHICLE INSPECTION REPORT

RE16LLA

Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	16/04/2016	Body Style	Hatchback	Last service miles	60,474
Year	2016	Keys	2	MOT Due	15/04/2027
Mileage	65,000 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	6	Doors	5
VIN	WF0DXXGAKDFT47052	Last service date	18/03/2025		

£100 ADDITIONAL FEE.

Last service 18/03/2025 at 60,474 miles- 6 services Multiple panels require machine polish

Tyres


NSF	HANKOOK	3.0mm
NSR	BUDGET	5.0mm
OSF	PIRELLI	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Cloth seat trim
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Dented
With Paint Damage



3: Wheel osr
Scratched
Over 50mm



4: Bumper Rear
Poor Previous Repair
Poor Paint



5: Fuel Flap
Missing
Replace



6: Wheel nsr
Scratched
Over 50mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK