

# VEHICLE INSPECTION REPORT

**YH13UZU**

## Mini Coupe 1.6 Cooper S 3dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	03/06/2013	VIN	WMWSX32000T442856	Number of stamps	6
Year	2013	Body Style	Coupe	Last service date	30/04/2025
Mileage	127,961 Miles Warranted	Keys	1	MOT Due	02/07/2026
Fuel Type	Petrol	Service history	Yes	Gearbox	MANUAL
Colour	RED	Service documents	Service Book	Gears	6

### £90 ADDITIONAL FEE

Last service 30/04/2025 mileage not recorded- 6 services (3 main dealer)

MOTs in 2022 and 2023 both recorded at 101,672 miles on MOT history Multiple panels will require machine polish

### Tyres

NSF	MICHELIN	1.7mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	1.8mm
OSR	MICHELIN	5.0mm

### Spare

## Features


- Bluetooth connection
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Body coloured bumpers
- Front armrest
- Drivers airbag
- Central locking
- Alloy wheels
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Passenger airbag
- Remote central locking
- Telephone
- Air conditioning
- Solid Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Door osf  
Dented  
With Paint Damage



2: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



3: Qtr Panel osr  
Chipped  
1 To 5




4: Wheel osr  
Corroded  
Light



5: Bumper Rear  
Chipped  
1 To 5



6: Qtr Panel nsr  
Chipped  
1 To 5



7: Door nsf  
Chipped  
Edge Chip



8: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



9: Wheel nsf  
Scratched  
Over 50mm



10: Bonnet  
Chipped  
Multiple Chips



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint



12: Bumper Front  
Chipped  
Multiple Chips



13: Screen Front  
Chipped  
Up To 10mm



14: Roof  
Chipped  
1 To 5

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK