



VEHICLE INSPECTION REPORT

SL63VMG

Kia Sportage 2.0 CRDi KX-4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/11/2013	Body Style	Estate	Last service miles	130,685
Year	2013	Keys	1	MOT Due	Expired
Mileage	133,283 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	ORANGE	Number of stamps	8		
VIN	U5YPC813NDL413948	Last service date	26/11/2024		

£100 ADDITIONAL FEE Last service 26/11/2024 @ 130685 miles (8 SERVICES 5 MAIN DEALER) book + print

Tyres


NSF	MICHELIN	1.7mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	1.7mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osf
Dented
2 Or Less UpTo 10mm



3: Wheel osf
Corroded
Light



4: Wheel osr
Corroded
Light



5: Wheel nsr
Corroded
Light



6: Door nsf
Dented
Between 10mm + 30mm



7: Wheel nsf
Corroded
Light



8: Bonnet
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		