



VEHICLE INSPECTION REPORT

GY65OSL

Ford Fiesta 1.5 TDCi Van

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	17/12/2015	VIN	WF0RXXGAKRFM66043	CAP Below	£1,125.00
Year	2015	Body Style	Car Derived Van	Gearbox	MANUAL
Mileage	74,124 Miles Warranted	MOT Due	16/12/2025	Gears	5
Fuel Type	Diesel	CAP Clean	£1,900.00		
Colour	BLACK	CAP Average	£1,575.00		

£100 ADDITIONAL FEE Spanner Light On Dash

Tyres		
NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	EVENT	5.0mm
Spare		

Features


- Radio/CD
- Drivers airbag
- Air conditioning
- Passenger airbag
- Front electric windows
- Central locking
- Metallic Paint
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Door osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osf
Dented
Over 2 UpTo 10mm




4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Bumper Rear
Dented
With Paint Damage



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsf
Chipped
1 To 5



9: Bumper Front
Hole
Over 25mm



10: Bonnet
Scratched
Over 25mm Not Thru Paint



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK