



# VEHICLE INSPECTION REPORT

**KV20WFR**

## Seat Leon 1.5 TSI EVO 150 FR [EZ] 5dr DSG

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	03/03/2020	Body Style	Hatchback	Last service miles	70,000
Year	2020	Keys	2	MOT Due	02/03/2027
Mileage	78,247 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	RED	Number of stamps	7	Doors	5
VIN	VSSZZZ5FZLR045011	Last service date	09/10/2025		

Last service 09/10/2025 at 70,000 miles- 7 services

### Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	3.0mm
OSR	GOODYEAR	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
Edge Chip



4: Bumper Rear  
Chipped  
1 To 5



5: Tailgate  
Dented  
Over 30mm



6: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



7: Wheel nsr  
Scratched  
Up To 50mm



8: Door nsf  
Chipped  
Edge Chip



9: Bumper Front  
 Scratched  
 25 to 100mm Thru Paint



10: Bumper Front  
 Chipped  
 Multiple Chips



11: Bonnet  
 Chipped  
 1 To 5

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK