



# VEHICLE INSPECTION REPORT

**GK59VMH**

## Mini Hatchback 1.6 Cooper S 3dr Auto

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	26/09/2009	Body Style	Hatchback	Last service miles	50,365
Year	2009	Keys	2	MOT Due	27/09/2026
Mileage	68,246 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	8	Doors	3
VIN	WMWMF72080TV07018	Last service date	12/09/2023		

Last service 12/09/2023 at 50,365 miles- 8 services  
 Mileage of MOT in 2012 recorded incorrectly on MOT history

### Tyres

NSF	SUNNY	5.0mm
NSR	DUNLOP	5.0mm
OSF	SUNNY	Damaged
OSR	DUNLOP	5.0mm
Spare		

## Features


- Bluetooth connection
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Partial leather seat trim
- Rear parking sensor
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsf  
Dented  
Over 30mm



5: Door nsf  
Chipped  
1 To 5



6: Sill Panel Trim ns  
Scratched (Painted)  
UpTo 25mm Thru Paint



7: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



8: Qtr Panel nsr  
Chipped  
1 To 5



9: Wheel nsr  
Scratched  
Over 50mm



10: Wheel osr  
Scratched  
Over 50mm



11: Door osf  
Chipped  
Edge Chip



12: Screen Front  
Chipped  
UpTo 10mm



13: Wheel osf  
Scratched  
Over 50mm



14: Tyre osf  
Damaged  
Replace



15: Roof  
Chipped  
1 To 5

### Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK