



VEHICLE INSPECTION REPORT

GD23FTT

Seat Leon 1.0 TSI EVO FR 5dr

nama
 GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	30/06/2023	Body Style	Hatchback	Last service miles	8,388
Year	2023	Keys	2	Gearbox	MANUAL
Mileage	11,762 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	RED	Number of stamps	2		
VIN	VSSZZZKL7PR059270	Last service date	06/05/2025		

£90 ADDITIONAL FEE

Last service 06/05/2025 at 8388 miles- 2 main dealer services

Tyres


NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Qtr Panel osr
Chipped
1 To 5




6: Door osr
Chipped
Edge Chip



7: Door osf
Chipped
Edge Chip



8: Wing osf
Chipped
1 To 5



9: Screen Front
Chipped
UpTo 10mm



10: Centre Console Front
Scuffed
UpTo 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		