

VEHICLE INSPECTION REPORT

GY16ZDO

Toyota Aygo 1.0 VVT-i X-Play 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
 GRADE
3

Details

Reg. date	31/05/2016	Body Style	Hatchback	Last service miles	51,635
Year	2016	Keys	2	MOT Due	14/07/2026
Mileage	55,483 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	RED	Number of stamps	9	Doors	5
VIN	JTDKGN10N177633	Last service date	11/07/2025		

Clutch replaced 18/03/2025 at 48459 miles.
 Last service 11/07/2025 at 51635 miles (9 services (2 main dealer)).

Tyres


NSF	BUDGET	4.0mm
NSR	HIFLY	4.0mm
OSF	BUDGET	4.0mm
OSR	HIFLY	4.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Front electric windows
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Solid Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Air conditioning
- ABS
- Tyre pressure monitor
- Steel wheels

Photos





Condition Check



Damage Photos



1: Wing of
Dented
Over 30mm



2: Other
N/A
N/A



3: Door osf
Chipped
Edge Chip



4: Door osr
Scratched
Over 25mm Thru Paint



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Other
N/A
N/A



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsf
Chipped
1 To 5



10: Other
N/A
N/A



11: Bonnet
Chipped
1 To 5



12: Bumper Front
Chipped
Multiple Chips



13: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK