



VEHICLE INSPECTION REPORT

CN18LXW

Citroen C3 1.2 PureTech Feel 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/04/2018	Body Style	Hatchback	Last service miles	74,133
Year	2018	Keys	2	MOT Due	06/09/2026
Mileage	99,163 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	WHITE	Number of stamps	3	Doors	5
VIN	VF7SXHMP6JT557042	Last service date	03/07/2023		

Last Service - 03.07.2023 at 74133 miles (3 services) Exhaust blowing
 Spanner light on dash
 Rear middle headrest missing

Tyres

NSF	HANKOOK	4.0mm
NSR	BUDGET	4.0mm
OSF	HANKOOK	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim
- Cruise control
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Wheel of
Corroded
Light



2: Wing of
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Bumper Rear
Chipped
1 To 5



7: Tailgate
Poor Previous Repair
Paint Flake



8: Door nsr
Chipped
Edge Chip



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Chipped
1 To 5



11: Other
N/A
N/A



12: Wing nsf
Chipped
1 To 5



13: Wheel nsf
Corroded
Light



14: Bumper Front
Poor Previous Repair
Poor Paint



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm



17: Roof
Scratched
Over 25mm Thru Paint



18: C Post os
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK