



VEHICLE INSPECTION REPORT

GP21EFF

Volkswagen Golf 1.5 TSI 150 Life 5dr

nama
 GRADE
4

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	24/07/2021	Body Style	Hatchback	Last service miles	9,516
Year	2021	Keys	2	MOT Due	17/03/2027
Mileage	10,873 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	BLUE	Number of stamps	4	Doors	5
VIN	WVVZZZCDZNW000710	Last service date	17/07/2025		

Last service 17/07/2025 at 9516 miles- 4 main dealer services

Tyres

NSF	AVON	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	Damaged
OSR	NEXEN	Damaged
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check




Damage Photos



1: Tyre osf
Damaged
Replace



2: Tyre osr
Damaged
Replace



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Poor Previous Repair
Paint Flake



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Chipped
1 To 5



9: Bumper Rear
 Poor Previous Repair
 Poor Paint



10: Door osr
 Scratched
 UpTo 25mm Thru Paint



11: Door osf
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK