



# VEHICLE INSPECTION REPORT

**CL60DSL**

## Mazda CX-5 2.2d Sport Nav+ 5dr

nama  
 GRADE  
**3**

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

### Details

Reg. date	10/12/2018	Body Style	Estate	Last service miles	153,083
Year	2018	Keys	2	MOT Due	09/12/2026
Mileage	159,381 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	13		
VIN	JMZKF6W1600781531	Last service date	04/12/2025		

£100 ADDITIONAL FEE

Last service 04/12/2025 at 153,083 miles- 13 services (3 main dealer) POOR BRAKES

### Tyres

NSF	GOODYEAR	3.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	3.0mm
OSR	GOODYEAR	4.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Air conditioning
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
1 To 5



2: Door osr  
Chipped  
1 To 5



3: Bumper Rear  
Chipped  
1 To 5



4: Door nsr  
Chipped  
1 To 5



5: Door nsf  
Chipped  
1 To 5




6: Wing nsf  
Chipped  
1 To 5



7: Wheel nsf  
Scratched  
Up To 50mm



8: Bumper Front  
Chipped  
Multiple Chips



9: Bonnet  
Chipped  
Multiple Chips



10: Roof  
Chipped  
1 To 5



11: Bumper Front  
Scratched  
25 to 100mm Thru Paint



12: Door osf  
Dented  
Over 30mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK