



# VEHICLE INSPECTION REPORT

**GD16ZZU**

## Volkswagen Golf 1.4 TSI 125 Match Edition 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**4**

### Details

Reg. date	15/06/2016	Body Style	Hatchback	Last service miles	63,037
Year	2016	Keys	2	MOT Due	14/06/2026
Mileage	67,054 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	8	Doors	5
VIN	WVVZZZAUZGP125269	Last service date	09/06/2025		

Last service 09/06/2025 at 63037 miles (8 services (3 main dealer). Error visit workshop message displays on dash

### Tyres

NSF	GOODYEAR	5.0mm
NSR	FALKEN	5.0mm
OSF	GOODYEAR	4.0mm
OSR	GENERAL TIRE	5.0mm
Spare		

### Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

### Photos





## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wing osf  
Chipped  
1 To 5



3: Door osf  
Chipped  
1 To 5



4: Door osr  
Dented  
2 Or Less UpTo 10mm



5: Door osf  
Chipped  
Edge Chip



6: Bumper Rear  
Hole  
Over 25mm



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Door nsf  
Chipped  
Edge Chip



9: Door nsf  
Chipped  
1 To 5



10: Wing nsf  
Dented  
With Paint Damage



11: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



12: Wheel nsf  
Scratched  
Over 50mm



13: Bumper Front  
Scratched  
25 to 100mm Thru Paint



14: Bonnet  
Chipped  
1 To 5



15: Screen Front  
Chipped  
Over 10mm



16: Door Mirror Assy osf  
Scratched (Painted)  
Over 25mm Thru Paint

**Interior**

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

**Vehicle Inspection Report**

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK