



VEHICLE INSPECTION REPORT

WN61UZO

Nissan Juke 1.6 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	21/10/2011	Body Style	Hatchback	Last service miles	45,581
Year	2011	Keys	2	MOT Due	06/11/2026
Mileage	53,344 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	5	Doors	5
VIN	SJNFAAF15U6138430	Last service date	10/05/2022		

last service 10/5/22 @ 45,581 miles (5 service 3 main dealer) book & print replaced timing chain on 26/3/24 @ 48,703 miles
 Vehicle has had a color Change Previously Red Exhaust blowing
 Car has been wrapped

Tyres


NSF	GENERAL TIRE	4.0mm
NSR	BRIDGESTONE	Damaged
OSF	GENERAL TIRE	Damaged
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Digital radio
- Space saver spare wheel
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Wheel nsf
Scratched
Over 50mm



3: Door nsf
Scratched
UpTo 25mm Thru Paint



4: Door nsr
Chipped
1 To 5



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Door osf
Chipped
Edge Chip



7: Wheel osf
Scratched
Over 50mm



8: Seat Base Cover osf
Torn
UpTo 3mm



9: Wing nsf
 Scratched
 UpTo 25mm Thru Paint



10: Tyre osf
 Damaged
 Replace



11: Tyre nsr
 Damaged
 Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK