



VEHICLE INSPECTION REPORT

DO10TOO

Jaguar XJ 3.0d V6 Portfolio 4dr Auto [8]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/09/2012	Keys	2	CAP Clean	£7,950.00
Year	2012	Service history	Yes	CAP Average	£7,075.00
Mileage	56,978 Miles Warranted	Service documents	Service Book	CAP Below	£6,250.00
Fuel Type	Diesel	Number of stamps	12	Gearbox	AUTOMATIC
Colour	WHITE	Last service date	18/07/2024	Gears	8
VIN	SAJAC1623DENV39667	Last service miles	55,006	Doors	4
Body Style	Saloon	MOT Due	09/08/2025		

Last Service - 18.07.2024 at 55006 miles (12 services)

Tyres

NSF	DUNLOP	5.0mm
NSR	DUNLOP	5.0mm
OSF	DUNLOP	5.0mm
OSR	DUNLOP	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable passenger seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Telephone
- Air conditioning
- Front armrest
- Solid Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Qtr Panel osr
Dented
Over 30mm



2: Bonnet
Chipped
1 To 5

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		