



VEHICLE INSPECTION REPORT

LE21BWO

Skoda Kamiq 1.0 TSI 110 SE Drive 5dr DSG

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	10/06/2021	Body Style	Hatchback	Last service miles	12
Year	2021	Keys	2	MOT Due	Expired
Mileage	14,423 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	4	Doors	5
VIN	TMBHR6NW3M3101515	Last service date	05/06/2025		

£100 ADDITIONAL FEE

Last service 05/06/2025 at 12.109 miles- 4 main dealer services Servydue message displayed

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm

Spare

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door nsf
Chipped
Multiple Chips



14: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK