



# VEHICLE INSPECTION REPORT

**WU74NLJ**

## Hyundai I10 1.0T [90] N Line 5dr [Nav]

nama  
 GRADE  
**1**

| Inspection      |    | Vehicle |           |
|-----------------|----|---------|-----------|
| Serious Damage? | No | VAT     | Margin    |
|                 |    | V5      | Photocopy |

### Details

|           |                       |                   |            |                    |            |
|-----------|-----------------------|-------------------|------------|--------------------|------------|
| Reg. date | 09/09/2024            | Body Style        | Hatchback  | Last service miles | 6,154      |
| Year      | 2024                  | Keys              | 2          | MOT Due            | 08/09/2027 |
| Mileage   | 6,435 Miles Warranted | Service history   | Yes        | Gearbox            | MANUAL     |
| Fuel Type | Petrol                | Service documents | Printout   | Gears              | 5          |
| Colour    | GREY                  | Number of stamps  | 1          | Doors              | 5          |
| VIN       | NLHDR51D6SZ306129     | Last service date | 30/10/2025 |                    |            |

Last Service - 30.10.2025 at 6154 miles (1 main dealer services)

NO V5 PHOTOCOPY V5C ONLY

VEHICLE ADAPTED FOR TOWING WITH A FRAME VEHICLE ADAPTED FOR TOWING WITH A FRAME

### Tyres

|       |         |       |
|-------|---------|-------|
| NSF   | HANKOOK | 5.0mm |
| NSR   | HANKOOK | 5.0mm |
| OSF   | HANKOOK | 5.0mm |
| OSR   | HANKOOK | 5.0mm |
| Spare |         |       |

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bumper Front  
Chipped  
1 To 5



2: Bonnet  
Chipped  
1 To 5

## Interior

**Carpet Condition**      OK  
**Seat Condition**        OK

**Upholstery Condition**    OK  
**Odour**                      No

## Vehicle Inspection Report

---

**Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                          |    |  |    |
|--------------------------|----|--|----|
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | Service indicator light illuminated            | OK |
| ABS light illuminated    | OK |  |    |
| Windows                  | OK | Radio  | OK |
| Sat nav                  | OK | Steering                                       | OK |